

Components

FLARE FITTINGS for R-410a, R-32.....



FLARE FITTINGS BRASS/BRASS - Female SAE Swivel Nut with Long Tan Copper Gasket x ODS solder

- Female SAE swivel nut with brass bush ODS solder;
- Long Tan Copper Gasket for easy connections in horizontal and down position;
- For all refrigerants (except R-717 Ammonia).



FFBR- 6 6

Model	Description
FFB- 4 4	Flare Fitting Brass/Brass 45° 1/4" (7/16" 20UNF) Female SAE swivel Nut with Long Tan Copper Gasket x 1/4" ODS solder. R4-10a, R-32.
FFB- 5 5	5/16" F. SAE x 5/16" (8 mm.) ODS solder R410a, R32.
FFB- 6 6	3/8" F. SAE x 3/8" ODS solder. R410a, R32.
FFB- 8 8	1/2" F. SAE x 1/2" ODS solder. R410a, R32.
FFB-1010	5/8" F. SAE x 5/8" ODS solder. R410a, R32.
FFB-1212	3/4" F. SAE x 3/4" ODS solder. R410a, R32.
FFB-1414	7/8" F. SAE x 7/8" ODS solder. R410a, R32.
FFB- 4 6MM	Flare Fitting Metric 1/4" (7/16" 20UNF) Female SAE swivel Nut with Long Tan Copper Gasket x 6 mm. ODS solder.
FFB- 610MM	3/8" F. SAE x 10 mm. ODS solder.
FFB- 812MM	1/2" F. SAE x 12 mm. ODS solder.
FFB-1016MM	5/8" F. SAE x 16 mm. ODS solder.
FFB-1218MM	3/4" F. SAE x 18 mm. ODS solder.
FFB-1422MM	7/8" F. SAE x 22 mm. ODS solder.

REDUCING FLARE FITTINGS BRASS/BRASS - Female SAE Swivel Nut with Long Tan Copper Gasket x ODS - ODF solder



FFBR- 6 5

Model	Description
FFBR- 5 4	Flare Fitting Reducing 1/4" (7/16" 20UNF) Female SAE swivel Nut with Long Tan Copper Gasket x 1/4" ODS solder. R-410a, R-32
FFBR- 6 5	3/8" F. SAE x 5/16" ODS solder R410a, R32.
FFBR- 8 6	1/2" F. SAE x 3/8" ODS solder R410a, R32.
FFBR-10 8	5/8" F. SAE x 1/2" ODS solder R410a, R32.
FFBR-1210	3/4" F. SAE x 5/8" ODS solder R410a, R32.
FFBR-1412	7/8" F. SAE x 3/4" ODS solder.

FFBR- 5 6MM	Reducing Metric 1/4" (7/16" 20UNF) Female SAE swivel Nut with Long Tan Copper Gasket x 6 mm. ODS - 10 mm. ODF solder.
FFBR- 6 8MM	3/8" F. SAE x 8 mm. ODS solder.
FFBR- 810MM	1/2" F. SAE x 10 mm. ODS solder.
FFBR-1012MM	5/8" F. SAE x 12 mm. ODS solder.
FFBR-1014MM	5/8" F. SAE x 14 mm. ODS solder.
FFBR-1216MM	3/4" F. SAE x 16 mm. ODS solder.
FFBR-1218MM	3/4" F. SAE x 18 mm. ODS solder.
FFBR-1418MM	7/8" F. SAE x 18 mm. ODS solder.

FLARE FITTINGS - STAINLESS STEEL

- Brass swivel Nut Female SAE with Stainless Steel/ Copper bush ODS solder;
- Long Tan Copper Gasket for easy connections in horizontal and down position;
- For all refrigerants (except R-717 Ammonia).



FFS- 6 6

Model	Description
FFS- 4 4	Flare Fittings Stainless Steel 45° 1/4" (7/16" 20UNF) Female SAE swivel nut with Long Tan Copper Gasket x 1/4" ODS solder. R-410a, R-32.
FFS- 5 5	5/16" F. SAE x 5/16" ODS solder. R410a, R32.
FFS- 6 6	3/8" F. SAE x 3/8" ODS solder. R410a, R32.
FFS- 8 8	1/2" F. SAE x 1/2" ODS solder. R410a, R32.
FFS-1010	5/8" F. SAE x 5/8" ODS solder. R410a, R32.
FFS-1212	3/4" F. SAE x 3/4" ODS solder. R410a, R32.
FFS-1414	7/8" F. SAE x 7/8" ODS solder. R410a, R32.

FLARE FITTINGS - SPARE PARTS



B3- 6

Model	Description
B3- 4	Long Tan Copper Gasket for 1/4" Female SAE.
B3- 5	5/16" F. SAE.
B3- 6	3/8" F. SAE.
B3- 8	1/2" F. SAE.
B3-10	5/8" F. SAE.
B3-12	3/4" F. SAE.
B3-14	7/8" F. SAE.